



TEST REPORT

Reference No. : SZ2019090334E

Date: Sep.17, 2019

Page No.: 1 of 6

Client: Techfo Limited

Address: Room 5, Unit S-V, 6/F, Valiant Industrial Centre, 2-12 Au Pui Wan Street, Fo Tan,
Shatin, Hong Kong

The following merchandise was (were) submitted and identified by the client as:

Name of Product: cabseat

Sample Model: CS-001

Main Material: HDPE

Lot No.: 2019-01

Designer & Address: Secure Bathtub LLC

Economic Development Bank Building, Suite 202, 638 Aldebaran St.,
San Juan, PR 00920

Sample Received: Sep.10, 2019

Test date: Sep.16, 2019

Test Result(s): For further details, please refer to the following page(s)

Prepared By :

Kun Wang

Kun Wang

Reviewed By :

Wendy Zhou

Wendy Zhou



Issued By :

Ian Xu

Ian Xu



SZ2019090334E

STQ Testing Services Co., Ltd.

Add.:2-1-B, China-singapore science industrial zone I, 8# zhanye road, sip suzhou, China

Tel.: +86/(0)512 62956572

Fax: +86/(0)512 87661802

Web: www.stq-cert.com

Technical service: TS@stq-cert.com

Customer service: CS@stq-cert.com

TEST REPORT

Reference No. : SZ2019090334E

Date: Sep.17, 2019

Page No.: 2 of 6


Summary of test result:

No.	Test Item	Test Requirement	Result	Conclusion
1	Loading test 120kg	Client's requirements	See 1.7	Pass

Statement: 1. The sample(s) was/were submitted and identified by the client. The test result is only reference for the sample.

2. Reproduced this report in partial is not effective, except for full copy.
3. The report is invalid without STQ official stamp.
4. The report without preparation, review, and issue signature is invalid.
5. Alter, add or delete itself is invalid.

Note: Pass : Meet the requirements;
Fail : Does not meet the requirements;
/ : Not Apply to the judgment.

Sample Receive:

STQ Testing Services Co., Ltd.

Add.:2-1-B, China-singapore science industrial zone I, 8# zhanye road, sip suzhou, China

Tel.: +86/(0)512 62956572

Fax: +86/(0)512 87661802

Web: www.stq-cert.com

Technical service: TS@stq-cert.com

Customer service: CS@stq-cert.com

TEST REPORT

Reference No. : SZ2019090334E

Date: Sep.17, 2019

Page No.: 3 of 6

1 LOADING TEST 120KG


1.1 TEST PARAMETERS AND KEY POINTS

Sample description	White plastic part	Test requirement	Client's requirements
Sample No.	SZ2019090334-1	Lab environmental condition	(23±2)°C & (50±5)%RH

1.2 TEST METHOD

According to client's requirements, test method is as follows:

- ① Two support bars of width 50mm place at the far end of product bottom.
- ② Apply uniform load 120kg stimulate a men sitting onto the central of product area (from 200x200 to 300x200).
- ③ 2hr measure bending deformation. Check if breaking of product.
- ④ Unload for 30min measure bending deformation to see if recovering of shape.
- ⑤ Repeat the test with the same sample again ③&④ and record.
- ⑥ Measure the final dimension (deformation) & any breaking of part.



1.3 SAMPLE CHECK BEFORE TEST

Sample No.	Appearance
SZ2019090334-1	No visible defect

1.4 SAMPLE INSTALLATION METHOD

See the photos in the test.

STQ Testing Services Co., Ltd.

Add.:2-1-B, China-singapore science industrial zone I, 8# zhanye road, sip suzhou, China

Tel.: +86/(0)512 62956572

Fax: +86/(0)512 87661802

Web: www.stq-cert.com

Technical service: TS@stq-cert.com

Customer service: CS@stq-cert.com

TEST REPORT

Reference No. : SZ2019090334E

Date: Sep.17, 2019

Page No.: 4 of 6

1.5 DEVIATION FROM TEST STANDARD

None

1.6 ACCEPTANCE CRITERIA


Measure the final dimension (deformation) & any breaking of part.

1.7 TEST RESULT

Sample No.	Test result	Conclusion
SZ2019090334-1	No deformation and breaking.	Pass

1.8 TEST EQUIPMENT

Equipment Name	Equipment No.	Model No.	Calibration Due
Load cell	STQ-E-2-050	U2B	Sep.10, 2020
Electric cylinder	STQ-E-2-074	ETH050M10	/

1.9 TEST PHOTO

STQ Testing Services Co., Ltd.

Add.:2-1-B, China-singapore science industrial zone I, 8# zhanye road, sip suzhou, China

Tel.: +86/(0)512 62956572

Fax: +86/(0)512 87661802

Web: www.stq-cert.com


Technical service: TS@stq-cert.comCustomer service: CS@stq-cert.com

TEST REPORT


Reference No. : SZ2019090334E

Date: Sep.17, 2019


Page No.: 5 of 6



Before test



During test



After test

STQ Testing Services Co., Ltd.

Add.:2-1-B, China-singapore science industrial zone I, 8# zhanye road, sip suzhou, China

Tel.: +86/(0)512 62956572

Fax: +86/(0)512 87661802

Web: www.stq-cert.com

Technical service: TS@stq-cert.com


Customer service: CS@stq-cert.com

TEST REPORT

Reference No. : SZ2019090334E

Date: Sep.17, 2019

Page No.: 6 of 6



--- END ---

STQ Testing Services Co., Ltd.

Add.:2-1-B, China-singapore science industrial zone I, 8# zhanye road, sip suzhou, China

Tel.: +86/(0)512 62956572

Fax: +86/(0)512 87661802

Web: www.stq-cert.com

Technical service: TS@stq-cert.com

Customer service: CS@stq-cert.com